Fall 2015 Levee Maintenance Deficiency Summary Report Overall LMA & Unit Ratings, including USACE Erosion Survey

Sacramento River Basin

ST0014 Sutter Maintenance Yard Murphy	Overall LMA Rating	Total LMA Miles						
Slough at M&T Ranch	U	0.83						
Rated Item		Maintena	nce Deficiancy		Enforc	ement	Design & Obsole	k System scence
Rated item	M Miles	U Miles	M + 4U Miles	Threshold %	M Miles	U Miles	M Miles	U Miles
Earthen Levee								
Vegetation	0.18		0.18	21.63%				
LMA Totals:	0.18	0.00	0.18	21.63%	0.00	0.00	0.00	0.00

Tuesday, January 05, 2016 16:52 Page 1 of 1

LMA District Cover Sheet Fall 2015 Levee Inspection Results

Sutter Maintenance Yard Murphy Slough at M&T Ranch

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)					
* Overall LMA Rating (Fall Only)			U						
	** Non-receipt of Su	mmer or Winter Inspe	ection Reports may effec	ct overall annual rating					
* SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall. FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports. This rating is not intended to be an indiction of risk.									
comments									

Unit Cover Sheet

Fall 2015 Levee Inspection Results

Sutter Maintenance Yard Murphy Slough at M&T Ranch

Waterway	Bank	Unit Miles
Unit No. 01 Murphy Slough at M&T Ranch	Left	0.83

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			U	
Date of Inspection	04/07/2015 - 04/07/2015		09/23/2015 - 09/23/2015	
DWR Inspector	Bob Duffey		Bob Duffey	
Accompanied By	Jason Cooper Sutter Maintenance Yard		Jason Cooper Sutter Maintenance Yard	

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

http://cdec.water.ca.gov/lma.html

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

Levee Inspection Report By Mile - Fall 2015

Sutter Maintenance Yard Murphy Slough at M&T Ranch

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Murphy Slough at M&T Ranch	Left	0.83	09/23/2015 09/23/2015	Bob Duffey

LM Start		Rating **	Α	Issue No.		2		
LM End		Issue Type +	Ма	Location *		N/A		
Earthen Levee				GPS La	atitud	e/Longitude		
Category				Start		End		
Item		s & Maintena	nce		0		0	
item	Manuals				0		0	
DWR ID	DWR_NA0	014_01_s _ 201	3_2					
		Action/	Comme	nts				
Inspector	Comments	: The LMA co	mpleted	flood fight	traini	ing in 2014.		

No Photos

Rating ** Issue No. 3 LM Start LM End Issue Type + Ма Location * N/A Earthen Levee GPS Latitude/Longitude Category Start End **Emergency Supplies &** Item Equipment DWR ID DWR_NA0014_01_s _ 2013_3 Action/Comments

No Photos

Inspector Comments: The LMA has adequate flood fight supplies and equipment.

LM Start		Rating **	Α	Issue No.		6		
LM End		Issue Type +	Ma	Location *		N/A		
Category Earthen Levee				GPS Latitude/Longitude				
Category				Start		End		
Item	Flood Pre	paredness &		0		0		
item					0		0	
DWR ID	DWR_NA0	014_01_s _ 201	3_6					
	Action/Comments							
Inspector (Inspector Comments: There is no O&M Manual for M&T Ranch.							

No Photos

* Location

LS: Land Side N/A: Not Applicable
WS: Water Side
CR: Crown

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain + Issue Type

Ma: Maintenance Deficiancy
Ob: Design & System Obsolescence
En: Enforcement

Levee Inspection Report By Mile - Fall 2015

Sutter Maintenance Yard Murphy Slough at M&T Ranch

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Murphy Slough at M&T Ranch	Left	0.83	09/23/2015 09/23/2015	Bob Duffey

LM Start	0.00	Rating **	М	Issue No.		1		
LM End	0.09	Issue Type +	Ma	Location *		WS		
Category Earthen Levee				GPS La	titud	le/Longitude		
Calegory	gory			Start		End		
Item	Vegetatio	egetation			34 °	39.666836 °		
пеш				-121.9596	12 °	-121.960897 °		
DWR ID	DWR_NA0	014_01_s _ 201	12_1					
	Action/Comments							
Elderberrie	Elderberries are blocking visibility and flood fight capability.							

No Photos

LM Start	0.00	Rating **	М	Issue No.		4	
LM End	0.09	Issue Type +	Ма	Location *		LS	
Category	Earthen Levee				GPS Latitude/Longitude		
Calegory				Start		End	
Item	Vegetatio	n		39.66770)8 °	39.666983	0
пеш				-121.95981	7 °	-121.960997	0
DWR ID	DWR_NA0	014_01_s _ 201	2_4				
		Action/	Commer	nts			

No Photos

Elderberries are blocking visibility and flood fight capability.

LM Start	0.00	Rating **	Α	Issue No.	5			
LM End	0.83	Issue Type +	Ма	Location *	WS			
Category Earthen Levee				GPS Latitude/Longitude				
Calegory				Start		End		
Item	Vegetatio	n		39.66698	8 °	39.670695 °		
iteiii				-121.96099	3°	-121.970383 °		
DWR ID DWR_NA0014_01_s _ 2012_5								
Action/Comments								

Control annual grass and weeds on the levee slopes and easements. Inspector Comments: Sutter Yard sprayed the slope to remove the vegetation.

Photo 1 of 2 : FA_2015_ST0014_372_5_20150910_00003.jpg



View of the vegetation along the waterside slope.

Levee Inspection Report By Mile - Fall 2015

Sutter Maintenance Yard Murphy Slough at M&T Ranch

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Murphy Slough at M&T Ranch	Left	0.83	09/23/2015 09/23/2015	Bob Duffey

LM Start	0.00	Rating **	Α	Issue No.	5 (cont)		
LM End	0.83	Issue Type +	Ма	Location *		WS	
Category	Earthen Levee			GPS Latitude/Longitude			
				Start		End	
Item	Vegetation			39.66698	38 °	39.670695	0
item				-121.960993	93 °	-121.970383	0
DWR ID	DWR_NA0014_01_s _ 2012_5						
Action/Comments							

Control annual grass and weeds on the levee slopes and easements. Inspector Comments: Sutter Yard sprayed the slope to remove the vegetation.



View of the slope with no vegetation.

LM Start	0.12	Rating **	Α	Issue No.		7	
LM End	0.83	Issue Type +	Ma	Location *		LS	
Category	Earthen Levee			GPS Latitude/Longitude			
				Start		End	
Item	Vegetation			39.6668	13 °	39.670697 °	
			-121.9610	58°	-121.970385 °		
DWR ID	DWR_ST0014_01_f _ 2015_7						
Action/Comments							

Action/Comments

Control annual grass and weeds on the levee slopes and easements. Inspector Comments: Sutter Yard sprayed the slope to remove the vegetation.

Photo 1 of 1 : FA_2015_ST0014_372_7_20151012_00005.jpg



View of the slope with no vegetation.